

Project: Chimney Repair


Description: Condition survey as of

2300 / 2200

7.21.2025

Key-To Do--Yellow= Brickwork Only Red= Cap only Orange= Brickwork + Cap

Completed-Green= chimney has been tuck pointed, cap repaired
Blue= chimney has been torn down & rebuilt






Service Drop Upgrade Tracker Map GREEN- Meter box and line running into breaker panel lead from DTE lines has been replaced. Replaced within 10 years. YELLOW- Meter box and line running into breaker panel lead from DTE lines has been replaced. Replaced within 10-20 years. WHITE- No updates. They are sharing a common line from DTE line and splitting the 2 meters. TO DO-288 service drops

2220 Pittsfield Blvd. Ann Arbor, MI 48104 (734) 971-0233 Fax: (734) 971-3421






2220 Pittsfield Blvd. Ann Arbor, MI 48104 (734) 971-0233 Fax: (734) 971-3421



Updated as of 7.21.2025

Foundation Condition Survey
KeyRED- Multiple cracks at corners w/ wall movement
YELLOW- Cracking
GREEN- Completed or Inspected and does not require
repair



2220 Pittsfield Blvd. Ann Arbor, MI 48104 (734) 971-0233 Fax: (734) 971-3421